

May 2017 Sheet 1 of 4




PHOTO LOCATION MAP

SCALE : |" = 80'

NOTES:

REPRESENTS LOCATION AND DIRECTION OF PHOTOGRAPH TAKEN BY BARTELT ENGINEERING ON JANUARY 26, 2016. SEE "PHOTOGRAPHIC DOCUMENTATION OF SITE CONDITIONS - 2016 AT ALOFT WINERY," FOR PHOTO DESCRIPTIONS.



Aloft Winery 430 Cold Springs Road Angwin, CA 94508 APN 024-340-010 & -011 Job No. 14-26 May 2017 Sheet 2 of 4







PHOTO LOCATION MAP

SCALE : |" = 80'


NOTES:

 $\overline{\diamondsuit}$ REPRESENTS LOCATION AND DIRECTION OF PHOTOGRAPH TAKEN BY BARTELT ENGINEERING ON JANUARY 26, 2016. SEE "PHOTOGRAPHIC DOCUMENTATION OF SITE CONDITIONS - 2016 AT ALOFT WINERY," FOR PHOTO DESCRIPTIONS.



Aloft Winery 430 Cold Springs Road Angwin, CA 94508 APN 024-340-010 & -011 Job No. 14-26 May 2017 Sheet 3 of 4





May 2017 Sheet 4 of 4

May 2017 Job No. 14-26



PHOTOGRAPHIC DOCUMENTATION OF SITE CONDITIONS AT ALOFT WINERY 430 COLD SPRINGS ROAD, NAPA COUNTY, CA APN 024-340-010 & -011



Photograph 1: Northwesterly view of vineyards and basin. January 26, 2016



Photograph 2: East northeasterly panoramic view of vineyard and frost protection fan. January 26, 2016





Photograph 3: North Northeasterly panoramic view of vineyard and basin. January 26, 2016



Photograph 4: North northwesterly panoramic view of vineyard and basin. January 26, 2016





Photograph 5: West northwesterly panoramic view of gravel access road, vineyard and basin. January 26, 2016



Photograph 6: Northerly panoramic view of gravel access road and vineyard. January 26, 2016





Photograph 7: Northeasterly panoramic view of rock lined swale, gravel access road and vineyard. January 26, 2016



Photograph 8: East northeasterly view of rock lined swale, gravel access road and vineyard. January 26, 2016





Photograph 9: East southeasterly view of rock lined swale, gravel access road and vineyard. January 26, 2016



Photograph 10: South southeasterly panoramic view of gravel access road, rock lined swale and basin. January 26, 2016





Photograph 11: South Southwesterly panoramic view of basin, gravel access road and vineyard. January 26, 2016



Photograph 12: West southwesterly panoramic view of vineyard from gravel access road. January 26, 2016





Photograph 13: West northwesterly panoramic view of vineyard from gravel access road. January 26, 2016



Photograph 14: Northeasterly view of rock lined swale and vineyard. January 26, 2016





Photograph 15: Northeasterly panoramic view of rock lined swale and vineyard. January 26, 2016



Photograph 16: East northeasterly panoramic view of rock lined swale and vineyard. January 26, 2016





Photograph 17: East southeasterly panoramic view of rock lined swale and vineyard. January 26, 2016



Photograph 18: South southeasterly panoramic view of rock lined swale, gravel access road and vineyard. January 26, 2016





Photograph 19: North northeasterly panoramic view of rock lined swale, gravel access road and vineyard. January 26, 2016



Photograph 20: East northeasterly panoramic view of rock lined swale, gravel access road and vineyard. January 26, 2016





Photograph 21: East southeasterly panoramic view of rock lined swale and vineyard from gravel access road. January 26, 2016



Photograph 22: South southeasterly panoramic view of rock lined swale, gravel access road and vineyard. January 26, 2016





Photograph 23: South southwesterly panoramic view of rock lined swale, gravel access road and vineyard. January 26, 2016



Photograph 24: Southeasterly view of gravel access road and vineyard. January 26, 2016





Photograph 25: Westerly panoramic view of gravel access road and vineyard. January 26, 2016



Photograph 26: Northwesterly panoramic view of vineyard. January 26, 2016





Photograph 27: Northerly panoramic view of vineyard from gravel access driveway. January 26, 2016



Photograph 28: Northeasterly panoramic view of vineyard from gravel access road. January 26, 2016





Photograph 29: Easterly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 30: Southeasterly panoramic view of gravel access road and vineyards. January 26, 2016





Photograph 31: Southerly panoramic view of gravel access road and vineyard. January 26, 2016



Photograph 32: Southwesterly panoramic view of gravel access road and vineyard. January 26, 2016





Photograph 33: Southeasterly view of a drainage course, vineyard, gravel access road and outlet Tee spreader. January 26, 2016



Photograph 34: Easterly view of a drainage course, vineyard, gravel access road and basin. January 26, 2016





Photograph 35: Northeasterly panoramic view of a frost protection fan, basin, riser and vineyard. January 26, 2016



Photograph 36: Easterly panoramic view of a basin, riser, gravel access road and vineyard. January 26, 2016





Photograph 37: Southeasterly panoramic view of gravel access road and vineyard. January 26, 2016



Photograph 38: Southerly panoramic view of forested area and basin outlet Tee spreader. January 26, 2016





Photograph 39: Southwesterly view of forested area and basin outlet Tee spreader. January 26, 2016



Photograph 40: Westerly panoramic view of forested area and vineyard. January 26, 2016





Photograph 41: Northwesterly panoramic view of vineyard and vineyard avenue. January 26, 2016



Photograph 42: Northerly panoramic view of vineyard, gravel access road and basin. January 26, 2016





Photograph 43: Westerly panoramic view of rock lined basin edge, gravel access road and vineyard. January 26, 2016



Photograph 44: Southwesterly panoramic view of the rock lined basin edge, basin and riser. January 26, 2016





Photograph 45: Southerly panoramic view of rock lined basin edge, riser and vineyard. January 26, 2016



Photograph 46: South southeasterly panoramic view of rock lined basin edge, gravel access road and vineyard. January 26, 2016





Photograph 47: Southeasterly panoramic view of rock lined basin edge, gravel access road and vineyard. January 26, 2016



Photograph 48: Southeasterly panoramic view of gravel access road, gravel access road and vineyard. January 26, 2016





Photograph 49: Easterly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 50: Northeasterly panoramic view of gravel access road at bend and vineyard. January 26, 2016





Photograph 51: Northerly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 52: Northwesterly panoramic view of vineyard and gravel access road. January 26, 2016





Photograph 53: Southerly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 54: South easterly panoramic view of gravel access road, vineyard and diversion swale. January 26, 2016





Photograph 55: Easterly panoramic view of gravel access road and vineyard. January 26, 2016



Photograph 56: Northeasterly panoramic view of gravel access road and vineyards. January 26, 2016





Photograph 57: Southwesterly view of gravel access road and vineyards. January 26, 2016



Photograph 58: Northwesterly panoramic view of gravel staging area for vineyard operations and vineyards. January 26, 2016





Photograph 59: Northwesterly panoramic view of gravel staging area, well and vineyard. January 26, 2016



Photograph 60: Westerly panoramic view of gravel staging area, gravel access road and vineyards. January 26, 2016





Photograph 61: Southwesterly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 62: Southerly panoramic view of vineyard from gravel staging area. January 26, 2016



Photograph 63: Southeasterly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 64: Easterly panoramic view of gravel access road and vineyards. January 26, 2016





Photograph 65: Northeasterly panoramic view of gravel staging area, gravel access road and vineyard. January 26, 2016



Photograph 66: Northeasterly panoramic view of gravel access road and vineyard. January 26, 2016





Photograph 67: Northerly panoramic view of vineyard from gravel access road. January 26, 2016



Photograph 68: Northwesterly panoramic view of vineyard from gravel access road. January 26, 2016





Photograph 69: Westerly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 70: Southwesterly panoramic view of gravel access road and vineyards. January 26, 2016





Photograph 71: Southerly panoramic view of vineyard from gravel access road. January 26, 2016



Photograph 72: Southeasterly panoramic view of vineyard. January 26, 2016





Photograph 73: Easterly panoramic view of gravel access road and vineyards. January 26, 2016



Photograph 74: Southwesterly view of gravel staging area and vineyards. January 26, 2016





Photograph 75: Southeasterly view of gravel access road and vineyard. January 26, 2016



Photograph 76: Easterly view of gravel access road and vineyards. January 26, 2016





Photograph 77: Southerly panoramic view of gravel access road, rock lined drainage course and vineyard. January 26, 2016



Photograph 78: Southwesterly panoramic view of gravel access road and vineyard. January 26, 2016





Photograph 79: Westerly panoramic view of gravel access road, vineyard and gravel access road. January 26, 2016



Photograph 80: Northwesterly panoramic view of gravel access road and vineyard. January 26, 2016





Photograph 81: Northeasterly panoramic view of gravel access road, rock lined drainage course and vineyard. January 26, 2016



Photograph 82: Easterly panoramic view of gravel access road and vineyard from gravel access road. January 26, 2016





Photograph 83: Southeasterly panoramic view of vineyard from gravel access road. January 26, 2016



Photograph 84: South southeasterly panoramic view of vineyard from gravel access road. January 26, 2016





Photograph 85: Northeasterly panoramic view of gravel access road, drainage course and trees. January 26, 2016



Photograph 86: Southeasterly panoramic view of gravel access road and rocks. January 26, 2016





Photograph 87: Southerly panoramic view of gravel access road and surrounding rocks. January 26, 2016



Photograph 88: Southwesterly panoramic view of gravel access road, mulched side slopes and vineyard. January 26, 2016





Photograph 89: Westerly panoramic view of gravel access road and vineyard. January 26, 2016



Photograph 90: Northwesterly panoramic view of edge of vineyard block and mulched hillside. January 26, 2016





Photograph 91: North northeasterly panoramic view of forest adjacent to the gravel access road. January 26, 2016



Photograph 92: South southwesterly panoramic view of gravel access road and trees. January 26, 2016





Photograph 93: West northwesterly panoramic view of gravel access road and pond (behind brush). January 26, 2016



Photograph 94: North northwesterly panoramic view of gravel access road and pond (behind brush). January 26, 2016





Photograph 95: North northeasterly panoramic view of gravel access road and abutting vegetation. January 26, 2016



Photograph 96: East northeasterly panoramic view of gravel access road and abutting vegetation. January 26, 2016





Photograph 97: East southeasterly panoramic view of abandoned pipe in vegetation adjacent to the gravel access road. January 26, 2016



Photograph 98: South southeasterly panoramic view of vegetation adjacent to gravel access road. January 26, 2016





Photograph 99: South southwesterly panoramic view of vegetation adjacent to gravel access road. January 26, 2016



Photograph 100: Westerly panoramic view of gravel access road and abutting vegetation. January 26, 2016





Photograph 101: Northwesterly panoramic view of vegetation adjacent to the gravel access road. January 26, 2016



Photograph 102: Northerly panoramic view of vegetation adjacent to the gravel access road. January 26, 2016





Photograph 103: Northeasterly panoramic view of vegetation and drainage course adjacent to the gravel access road. January 26, 2016



Photograph 104: Easterly panoramic view of gravel access road, drainage course and vegetation. January 26, 2016





Photograph 105: Southeasterly panoramic view of gravel access road and rock lined shoulder. January 26, 2016



Photograph 106: Southerly panoramic view of gravel access road and vegetation. January 26, 2016





Photograph 107: Westerly panoramic view of gravel access road, turnout and vegetation. January 26, 2016



Photograph 108: Northwesterly panoramic view of gravel access road, turnout and brush. January 26, 2016





Photograph 109: North northeasterly panoramic view of turnout and brush adjacent to the gravel access road. January 26, 2016



Photograph 110: East northeasterly panoramic view of turnout and brush adjacent to the gravel access road. January 26, 2016





Photograph 111: Easterly panoramic view of gravel access road and turnout with storage tent in the background. January 26, 2016



Photograph 112: Southeasterly panoramic view of gravel access road and abutting vegetation. January 26, 2016





Photograph 113: Southerly panoramic view of vegetation adjacent to the gravel access road. January 26, 2016



Photograph 114: Southwesterly panoramic view of gravel access road and vegetation. January 26, 2016





Photograph 115: Southwesterly panoramic view of well shed and trees adjacent to the gravel access road. January 26, 2016



Photograph 116: Westerly panoramic view of gravel access road and trees. January 26, 2016





Photograph 117: Northwesterly panoramic view of gravel access road and trees. January 26, 2016



Photograph 118: Northerly panoramic view of trees adjacent to gravel access road. January 26, 2016





Photograph 119: Northeasterly panoramic view of storage tent and residence. January 26, 2016



Photograph 120: East northeasterly panoramic view of storage tent, residence and garage. January 26, 2016





Photograph 121: East southeasterly panoramic view of gravel access road and garage. January 26, 2016



Photograph 122: Southeasterly panoramic view of gravel access road and residence. January 26, 2016





Photograph 123: Southerly panoramic view of trees adjacent to the gravel access road with well shed on the right. January 26, 2016



Photograph 124: Westerly panoramic view of gravel access road with well shed in the background. January 26, 2016





Photograph 125: Northwesterly panoramic view of gravel access road and residence. January 26, 2016



Photograph 126: Northerly panoramic view of gravel access road and residence. January 26, 2016





Photograph 127: Northeasterly panoramic view of trees adjacent to gravel access road with garage on right. January 26, 2016



Photograph 128: Easterly panoramic view of the garage from the gravel access road. January 26, 2016





Photograph 129: East southeasterly panoramic view of garage and residence from the gravel access road. January 26, 2016



Photograph 130: South southeasterly panoramic view of residence from the gravel access road. January 26, 2016





Photograph 131: Southerly panoramic view of trees adjacent to the gravel access road and the residence. January 26, 2016



Photograph 132: Northeasterly panoramic view of gravel access road towards Cold Springs Road. January 26, 2016





Photograph 133: East northeasterly panoramic view of trees adjacent to the gravel access road with neighboring driveway in the background. January 26, 2016



Photograph 134: East southeasterly panoramic view of trees adjacent to the gravel access road with neighboring driveway in the background. January 26, 2016





Photograph 135: Southerly panoramic view of gravel access road towards garage and residence. January 26, 2016



Photograph 136: Southwesterly panoramic view of trees, parking area and residence. January 26, 2016





Photograph 137: Northwesterly panoramic view of trees adjacent to gravel access road. January 26, 2016



Photograph 138: Northerly panoramic view of trees adjacent to the gravel access road with a neighboring residence in the background. January 26, 2016





Photograph 139: Northwesterly panoramic view of Cold Springs Road away from subject parcel. January 26, 2016



Photograph 140: Westerly panoramic view of Cold Springs Road and neighboring residence. January 26, 2016





Photograph 141: Southwesterly panoramic view of Cold Springs Road towards entrance to the subject parcel. January 26, 2016



Photograph 142: South southwesterly panoramic view of Cold Springs Road towards entrance to the subject parcel. January 26, 2016





Photograph 143: Southeasterly panoramic view of neighboring driveway entrance from Cold Springs Road. January 26, 2016



Photograph 144: East southeasterly panoramic view of neighboring driveway entrance from Cold Springs Road. January 26, 2016





Photograph 145: Northeasterly panoramic view of neighboring vineyard from Cold Springs Road. January 26, 2016



Photograph 146: Northerly panoramic view of neighboring vineyard from Cold Springs Road. January 26, 2016





Photograph 147: Easterly panoramic view of storage tent and the residence adjacent to the gravel access road January 26, 2016



Photograph 148: Southeasterly panoramic view of the residence from the gravel access road. January 26, 2016



Photograph 149: Southerly panoramic view of trees with the gravel access road in the background. January 26, 2016



Photograph 150: Southwesterly panoramic view of trees with the gravel access road in the background. January 26, 2016





Photograph 151: Westerly panoramic view of trees with the gravel access road in the background. January 26, 2016



Photograph 152: Northwesterly panoramic view of trees adjacent to the gravel access road. January 26, 2016





Photograph 153: Northerly panoramic view of trees adjacent to the gravel access road. January 26, 2016



Photograph 154: Northeasterly panoramic view of trees adjacent to the gravel access road. January 26, 2016