Disposal Facility Inspection Report (52) - Draft

Enforcement Agency:				Local Inspection ID:			
County of Napa							
SWIS Facility File Number (99-xx-9999)				Inspection Date			
28-AA-0002				9/28/2018			
X LEA Periodic	LEA Periodic CalRecycle Closed Sites C		Ca	alRecycle Focused			
LEA Focused CalRecycle Enforcement Agent C		Ca	alRecycle Periodic				
Inspection Time	Inspection Time 2.0 Time In			9:00 am	Time Out	11:00 am	
Facility Name			Received By				
Clover Flat Resource Recovery Park			Clov	Clover Flat Landfill, Inc.			
Facility Location 0			Own	Owner Name			
4380 Silverado Trail Road, Calistoga 94515							
Inspector A			Also	Iso Present (Name)			
Peter Ex k			Kay	aye Woodworth			

THE ABOVE FACILITY WAS INSPECTED FOR COMPLIANCE WITH APPLICABLE SECTIONS OF DIVISION 30 OF PUBLIC RESOURCES CODE (PRC) AND TITLE 14 AND TITLE 27 CALIFORNIA CODE OF REGULATIONS (CCR)

			-
V	Α	Permits	Comments
		PRC 44002 - Operator Authorized by SWF Permit	
		PRC 44004(a) - Significant Change	
		PRC 44014(b) - Operator Complies with Terms & Conditions	
		21640 - Title 27 Full permit review	
		21600 - Report of Disposal Site Information	
V	Α	Location Restrictions	Comments
		20270 - Airport Safety	
V	Α	Operating Criteria	Comments
		20510 - Disposal Site Records	
		20515 - MSWLF Unit Records	
		20517 - Document Approvals / Requirements	
		20520 - Signs	
		20530 - Site Security	
		20540 - Roads	
		20550 - Sanitary Facilities	
		20560 - Drinking Water Supply	
		20570 - Communications Facilities	
		20580 - Lighting	
V	Α	Personnel	Comments
		20590 - Personnel Health and Safety	
		20610 - Training	
		20615 - Supervision	
		20620 - Site Attendant	

X No Violations or Areas of Concern

V	Α	Confined Unloading	Comments
		20630 - Confined Unloading	
v	Α	Spreading/Compacting	Comments
		20640 - Spreading/Compacting	
		20650 - Grading of Fill Surfaces	
		20660 - Stockpiling	
۷	Α	Daily & Intermediate Cover	Comments
		20670 - Availability Cover Material	
		20680 - Daily Cover	
		20690 - Alternative Daily Cover	
		20695 - Performance Standards	
		20700 - Intermediate Cover	
		20686 - Beneficial ReUse	
۷	Α	Handling Equipment & Maintenance	Comments
		20710 - Scavenging / Salvaging / Storage	
		20720 - Non-Salvageable Items	
		20730 - Volume Reduction/Energy	
		Recovery	
		20740 - Equipment	
X	•	20750 - Site Maintenance	2
V	Α	Controls	Comments
		20760 - Nuisance Control	
		20770 - Animal Feeding	
		20780 - Open Burning / Burning Wastes	
		20790 - Leachate Control	
		20800 - Dust Control	
		20810 - Vector and Bird Control	
		20820 - Drainage and Erosion Control	
		20830 - Litter Control	
		20840 - Noise Control	
		20860 - Traffic Control	
		20870 - Hazardous Wastes	
		20880 - Medical Wastes	
		20890 - Dead Animals	
v	Α	20900 - Air Criteria Gas Monitoring & Control	Comments
v	~	20918 - Exemptions	
		20919 - Exemptions 20919 - Gas Control	
		20919 - Gas Control 20921 - Gas Monitoring and Control	
		20921 - Gas Monitoring and Control	
		20925 - Gas Monitoring 20925 - Perimeter Monitoring Network	
		20925 - Permeter Monitoring Network 20931 - Structure Monitoring	
		20931 - Structure Monitoring 20932 - Monitored Parameters	
		20932 - Monitoring Frequency	
		20933 - Monitoring Frequency 20934 - Reporting	

		20937 - Reporting and Control of Excessive Gas Concentrations	
		20939 - Control Excessive Gas Concentrations	
۷	Α	Closure	Comments
		21110 - Time Frame for Closure	
		21780 - Closure Plan	
		21860(f) - Schedule Review/Approval C/PC Plans	
۷	Α	Corrective Action	Comments
		22101 - Corrective Action Cost Estimate	
		22103 - Updated Corrective Action Cost Estimate	
V	Α	Tires	Comments
		17351 - Fire Prevention	
		17352 - Facility Access and Security	
		17353 - Vector Control Measures	
		17354 - Storage	
		17355 - Disposal	
		17356 - Indoor Storage	

Comments:

Draft wet-weather plan has been submitted to LEA for review. Winter pad and road have been established. Newly cut road routed south of the active face will have safety berm and a litter control fence has been installed. September safety training included Red Flag Warnings, and night monitoring.

The new facility manager, Brock Swan, started this week and will be working alternating weeks at the landfill until he

can be permanently relocated.

The compactor was down at the time of inspection, and two minor equipment accidents (no personnel injuries) were noted in the incident logs.