

A Tradition of Stewardship
A Commitment to Service

Department of Public Works

Milliken Creek Bridge At Trancas Street

Bridge No. 21C0051 August 19, 2014



Background


May 5, 2014




Photo: J.L. Sousa, courtesy Napa Valley Register










Interim Re-Striping (1)







Interim Re-Striping (2)





Interim Re-Striping (3)






Condition Assessment

Damaged railing, spandrel wall






Condition Assessment

Superficial Cracking






Condition Assessment

Scour





Environmental Setting

Historic Structure





- 1. Railing & Spandrel Wall Repair
- 2. Milliken Creek Bridge Widening
- 3. Monticello Road Bridge Widening
- 4. Milliken Creek Bridge Realignment






Layout Map






Railing & Spandrel Wall Repair






Milliken Creek Bridge Widening





Monticello Road Bridge Widening





Milliken Creek Bridge Realignment





Costs and Time Frames

Alt#	County cost		Total Cost	Time
1	\$710,000	0	\$710,000	3 years
2	\$440,000	\$3,410,000	\$3,850,000	10 years
3	\$300,000	\$2,350,000	\$2,650,000	5 years
4	\$388,000	\$2,992,000	\$3,380,000	4 years



Next Steps

- Staff to complete evaluation of alternatives
- Return to Board with recommendation
 - Alternative
 - Cost
 - Funding
- Initiate funding programming as needed





Questions?

