

Photos 420 Glass Mountain Road

The following photos were taken during a site inspection on Monday June 25, 2007. Some progress was made removing materials and unsafe structures from the property, however the shed converted to a dwelling remains.



Scrap metal and debris



Scrap metal and debris



Storage of household items



Storage of lumber and debris



Storage shed demolished, debris



Lean-to removed



Front yard partially cleaned-up



Shed converted to dwelling remains
and possibly occupied.

The following are photos taken on February 15, 2007 of the exteriors portions of the property during a multi- departmental inspection.



Storage of metal and debris



Storage of household materials



Failing lean-to and porch.



Combustible material storage



Failing shed




Debris and combustible materials

The following are photos were taken on February 15, 2007 of the converted shed to dwelling.



Shed converted to dwelling without permits
Electrical and plumbing building violations.



Interior of Shed converted to dwelling





Grey water systems installed without permits.



Photo voltaic electrical system installed without permits.